


MANOR PARK EXAMPLE OF  
BUS STOP ACCESSIBILITY  
IMPROVEMENT



BUS STOP ACCESSIBILITY IMPROVEMENTS  
FOR DISABILITY ACCESS USING CONCRETE  
BLOCKS AND PAVING SLABS

1 to 12  
Meridian Crt

BUS STOP CAGES  
TO BE REMARKED

BUS STOP ACCESSIBILITY IMPROVEMENTS  
FOR DISABILITY ACCESS USING CONCRETE  
BLOCKS AND PAVING SLABS

